

NASA Western Region MTTC November 2009

Monday	Tuesday	Wednesday	Thursday	Friday
2	3 Connector Cleaning	4 ESD/Cleanroom Recertification	5	6 RDO
Mechanical Assembly				
Q Course				
9 Mechanical Assembly Recert	10 ESD Control	11 Cleanroom Fundamentals Veterans Day	12 Connector Mate/Demate	13 Connector Cleaning
Soldered Electrical Connections NASA-STD-8739.3 Recert. 84-1				
Crimp. Cable & Harness NASA-STD-8739.4				
16 ESD/Cleanroom Recertification	17 Connector Mate/Demate	18	19	20 RDO
Crimp. Cable & Harness NASA-STD-8739.4 Recert				
Fiber Optic NASA-STD-8739.5				
23	24	25	26 Holiday Thanksgiving	27 Holiday
Soldered Electrical Connections NASA-STD-8739.3 Recert.				
30				RDO